

# Government of Rajasthan National Health Mission, Rajasthan 1 Department of Medical, Health & Family Welfare Services, Swasthya Bhawan, Tilak Marg, Jaipur

F. No. 23()/NHM/ISC/104-JE O & M Tender/2020-21/\  $6\,$   $6\,$ 

Date: 20 08 2020

## Clarification/Corrigendum/ Addendum

In reference to the NIB No.**MHS2021SLOB00715**( 73 dated 07.07.2020) the various representations/ clarifications/ queries received from the firms and issues raised by the Bidders in Pre-Bid meeting dated 13.07.2020 are examined by the competent authorities and technical committee. The following Corrigendum / Addendum is issued for inclusion in bid document as below:-

S.No	Present Cla	use		Amen	ded Clause	e		
1	only those be technically a the RFP. It is highligh most advant Ambulances Successful B	Clause no.11.14- C Evaluation of Finar I bid opening shall be idders who shall qua- is per the criteria laid ted that the bidder quageous bid (All twood bids) would be judged idder. The total oper inted according to properiod.	e done for allify a down in a down i	for on techni in the It is hi the m arithm		dders who the criter cuments. hat the bid ageous bid Turnkey nces bids)	tion of Propose all be considered all decorated all decora	al: lone lalify own oting ed on n
	Selection Crit	teria for L1 Bidder	Cost per	operational cost will be submitted according to proposed agreement period				
	2	Type  104 –JE vehicles of NHM  104 –JE vehicles on (Turnkey Basis)	Ambulances (NHM) A		s Type Ambulance s (NHM) Ce S (NHM) Ce Ambulan ce Ambulan ce S (NHM) Ce Ambulan ce S (NHM) Ce Ambulan ce S (NHM) CE S (NH	Total cost		
2	Clause no 1	1.16 -Appeals (Page	no39)	1	on ( Turnkey Basis)	B -Appeals s	C+D (Lo among bidders	west the



#### Clause no -9.3 Hardware Requirements(Page 3 no 28)

Vehicle status update (Off-Road): vii. Toggle button for Off-Road/On-Road ( Driver mobile app shall be used for real time update, if fails to do so off-road penalty will be imposed as per clause 7

## Clause no -9.3 Hardware Requirements(Page no 28)

vii. Vehicle status update (Off-Road): Toggle button for Off-Road/On-Road status.Driver mobile app shall be used for real time update, which has to be verified within 10 minutes by service provider and if it is found genuine at the level of Service Provider, then service provider shall arrange reserve ambulances so as to ensure uninterrupted functioning of the project. (Note-real time reporting of offline/onlineRecords for each & every instances shall be made available on portal).

- 1. Break down: -In case of break down, reserve ambulance shall be made available in average 4 hours.
- 2. Schedule Maintenance: -In case of reserve schedule maintenance ambulance shall be made available with no up time.

Note :- (In case of breakdown, if reserve ambulances are not made available or delayed at base location beyond specified time, then proportionate deduction (Aggregated Sum of delay hours) shall be applicable on off-road ambulances.

If the Service Provider fails to do so, offroad penalty shall be imposed as per clause 7

#### Clause - 4.1.2(Page no. 16) 4

Point no.03-Total fleet of 104 –JE should be operational all the time; In any condition no ambulance shall be off-road at any point of time. It shall be the duty of Service provider to keep the reserve ambulances to replace the off-road ambulancesto maintain the fleet operational all the time. In case it is not done so, Penalty will be imposed as per clause 7 (6).

Point no.10 -Major aggregates chassis and complete engine can be changed after due permission from NHM. Entry of this change has to be entered in vehicle registration certificate from District TransportAuthority.

## Clause - 4.1.2(Page no. 16)

Point no.03- Total fleet of 104 –JE should be operational all the time; In any condition, no ambulance shall be off-road at any point of time. It shall be the duty of the Service provider to keep the suitable/appropriate number of reserve ambulances to replace the off-road ambulances to maintain the fleet operational at all times. In case, it is not done so, Penalty shall be imposed as per clause 7 (6).

Point no.10-Major aggregates chassis and complete engine can be changed after due permission from NHM (in case of Government owned Ambulances/Vehicles). Entry of this change has to be entered in vehicle registration certificate issued from Appropriate TransportAuthority.

Clause 6.4-Responsibility of the serviceprovider(Page no. 21) Point no. 28-

The wordcertified"PCR"

Point no. 29- Any other medical emergency in case, 108 Ambulance of same area is busy or Mass casualty reported.

Clause 6.4-Responsibility of the serviceprovider(Page no. 21) Point no. 28 -

The word certified "PCR"shall be replaced by BTR(Beneficiary Trip records).

Point no. 29-Any other medical emergency in case of Mass casualty reported.

New Addition Point No. 33: It shall be responsibility of the Service Provider to provide/ensure 24x7 Uninterrupted Services, Any interruption /strike shall lead to strict action against the Service Provider, including penalties as prescribed and even forfeiture of Performance Security if decided so by MD, NHM.

Point No. 34: Issues related to Manpowe/HR shall be dealt by Service Provider only. Under any circumstances, NHM will not be involved in HR issues of Service Provider.

Clause 6.7-Investment andownership

(Page no. 22)

All movable and immovable assets created in the project will be the property of RSHS (NHM), Government of Rajasthan. Account of such assets shall be maintained properly. The assets will have to be handed over to the Government on completion/termination of the agreement in proper working condition. Service Provider shall ensure to send the detailed information on monthly basis of the assets procured in that particular month.

## Clause6.7-Investment andownership (Page no. 22)

movable (Except Reserve Ambulance/ Vehicles) and immovable assets created in the project shall be the property of RSHS (NHM). Government of Rajasthan. Account of such assets shall be maintained properly. The assets& the accounts so created shall have to be handed over to the Government completion/termination agreement in proper working condition subject to clause 6.1. Service Provider shall ensure to send the detailed information on monthly basis of the assets procured in that particular month.

7 Clause no. 11.31 -Performance Security( Page no 45)

> a) The bidder whose proposal is accepted and Award issued shall have to deposit Performance Security of an amount of 5% of the total project cost to be calculated on the basis of rates received in the RFP along with signing of the agreement. Amount of Bid Security can be adjusted into the Performance

Clause no. 11.31 -Performance Security(Page no 45)

a) The bidder whose proposal is accepted and Award issued shall have to deposit Performance Security of an amount of 2.5 % of the total project cost to be calculated on the basis of rates received in the RFP along with signing of the agreement. Amount of Bid Security can



security. In case of Small Scale Industries (SSI) of Rajasthan, it shall be 1% of the amount of quantity ordered for supply of goods and in case of sick industries, other than SSI, whose cases are pending before the Board of Industrial and Financial Reconstruction (BIFR), it shall be 2% of the amount of supply order.

- a. Performance Security is required for due performance of the agreement. Non submission of Performance security within the specified time may also lead to forfeiture of the Bid Security.
- b. Forfeiture of Security Deposit: Performance Security amount in full or part may be forfeited, including interest, if any, in the following cases:-
  - When any terms and condition of the contract is breached.
  - ii. When the bidder fails to make complete supply as per the scope of RFP.

be adjusted into the Performance security. In case of sick industries, other than SSI, whose cases are pending before the Board of Industrial and Financial Reconstruction (BIFR), it shall be 1 % of the amount of supply order.

- a. Performance Security is required for due performance of the agreement. Non submission of Performance security within the specified time may also lead to forfeiture of the Bid Security.
- b. Forfeiture of Security Deposit: Performance Security amount in full or part may be forfeited, including interest, if any, in the following cases:-
- i. When any terms and condition of the contract is breached.
- ii. When the bidder fails to make complete supply as per the scope of RFP.

8 Clause - 3.1 <u>Technical Capacity( Page no.14)</u>

The bidder should have minimum 3 years of experience of operation of a fleet of atleast150 Ambulances/ **Emergency** vehicles each year (based on GPS & GIS services) in last 5years(2014-15 to 2018-19). Copy of Work orders and Certificates of Satisfactory services issued from various central / State Government / Corporations / Boards/ other Autonomous & Statutory bodies to whom services have been provided in past needs to be submitted along with theproposal mandatorily. In case of consortium/Joint Venture, the lead member shall be required to fulfill the Technical Eligibility criteria individually.

# Clause - 3.1 <u>Technical Capacity( Page</u>

The bidder should have minimum 2 years of experience of operation of a fleet of at Ambulances/ Emergency least 150 vehicles each year (based on GPS & GIS services) in the last 5 years(2015-16 to 2019-20).Copy of Work orders and Certificates of Satisfactory services issued from various Central / State Government / Corporations / Boards/ other Autonomous & Statutory bodies to whom services have been provided in past needs to be submitted along with the proposal mandatorily. In case of consortium/Joint Venture, any one

Off

09	2.4.1 Manpower for 104 JE services ( Page no 14)  Existing manpower, working in the implementation of the services may be given priority to the extent possible, subject to satisfactory performance.  The existing manpower retained subject to satisfactory services and other eligibility shall be entitled to atleast a 20% increase over the present wages (as on 07 Nov, 2019) Their wages will be in accordance with the provision of the Minimum Wages pertaining to skilled personnel.	member of the members shall be required to fulfill the Technical Eligibility criteria individually.  2.4.1 Manpower for 104 JE services ( Page no 14)  Existing manpower, working in the implementation of the services may be given priority to the extent possible, subject to satisfactory performance.  The existing manpower, retained subject to satisfactory services and other eligibility, shall be entitled to at least a 20% increase over the present wages (as on 07 Nov, 2019) Their wages will be in accordance with the provision of the Minimum Wages pertaining to skilled personnel.  As per details received from existing Service Provider, Gross salary for pilot on 07.11.2019 is annexed.(New Addition as Annexure-27)
10	3.2 Financial Capacity ( Page no.15) Bidder should have minimum Rs. 50 crores of annual average turnovers during last three Consecutive financial years starting from financial year 2016-17. Bidder needs to submit audited turnover statements by statutory auditor. For Purpose of verification of turnover, bidder is required to submit a certificate of turnover of concern financial years of Chartered Accountant. The Bidder should submit details of financial capability for the last three (3) financial years as per Annexure-13. The Qualifying Bid should be accompanied with the Audited Annual Reports including all financial statements of the Bidder. In case of a Consortium, Audited Annual Reports of all the Members of Consortium should besubmitted. The lead member of consortium /Joint venture shall be required to fulfil the 75% sharing of total Annual Average turnover of last three financial years.	3.2 Financial Capacity (Page no.15) Bidder should have minimum Rs. 60 crores of annual average turnovers during last three Consecutive financial years starting from financial year 2017-18. Bidder needs to submit audited turnover statements issued by statutory auditor. For Purpose of verification of turnover, bidder is required to submit a certificate of turnover of the said financial years issued by competent Chartered Accountant. The Bidder should submit details of financial capability for the last three (3) financial years as per Annexure-13. The Qualifying Bid should be accompanied with the Audited Annual Reports including all financial statements of the Bidder. In case of a Consortium, Audited Annual Reports of all the Members of Consortium should be submitted. The lead member of consortium / Joint venture shall be required to fulfil the 60% sharing of total Annual Average turnover of last three financial years (2017-18, 2018-19, 2019-20). The turnover shall be calculated on basis of Arithmetic sum of turnover of all members. The constitution of Consortium/Joint Venture shall not be changed without prior permission of MD, NHM during the entire tenure of the project.
11	Annexure -3 (Page no 56) -Annexure 29(A) & 29 (B)	Annexure -3 (Page no 56) Annexure 29(A) & 29 (B)shall be read as:  -Annexure 25-A (Point No. 1 to 18) - Annexure 25-B (Point No. 1 to 19)



12	for ambulance driver log their trip details, so (Response time) calcuments data will be integrated available on MIS reportionate deduct the day when it was a from the claims of Secutive shall be allowed is required to prepare only, using mobile aposms will be sent to the the EMT app as soon	ers: A mobile application is shall be mandatory to so that trip time culations can be accurate. It is not done to shall be imposed for reported nonfunctional crice Provider. No manual din any condition. Driver the BTR in electronic formation. An automated call / the destination hospital by as EMT staff enters the in the app by tap of a	For Ambulance Drivers: A mobile application for ambulance drivers shall be mandatory to log their trip details, so that trip time (Response time) calculations can be accurate. This data will be integrated with data base and available on MIS report. No manual entry shall be allowed in any condition. Driver is required to prepare BTR in electronic & Physical format, using mobile app. An automated call / SMS will be sent to the destination hospital by the pilot through Driver Mobile app in coordination with Call Centre as soon as the information is entered in the app.		
13		prototype approval:- NA I Parameters and	Clause 6.4 (Page No.21) New  Addition  33. Turnkey Ambulance prototype approval:-The Service Provider shall take prior approval of Prototype of Turnkey Ambulances that includes Branding, Stickering etc. by MD, NHM before deploying the vehicles /Ambulances.  Clause7 Operational Parameters and Penalty		
	( Page no- (Point no.2)  Permissible time for driver to start moving the 104-Janani express	Ambulance start time within permissible limit =2 Minutes)  1. More than 90% cases = No Penalty 2. 80 to 90 % cases = Rs. 100 /case 3. Less than 80 % cases = Rs. 200 / case	Permis Ambulance start time within permissible limit time =2 Minutes) for 1. More than 90% cases driver start time (within 2 minutes) = No Penalty the 2. Starts time(within 2 minutes) trends between 80 to 90 % cases = Rs. 100 /case/ defaults  3. Starts time (within 2 minutes) is reported Less than 80 % cases = Rs. 200 /		
15	1. Semi Urban A	Areas	case/defaults  1. Where ever in RFP, "Semi Urban Areas" is mentioned, Shall now be replaced as "Urban Areas".		
16	no. 2- Description of In case a valid call app is not serviced as Call verification pen- Calls received at	A, Point No. 3, Column Penalty)  / Request placed through a per RFP requirement then alty will be applicable. All the call center shall be a ted by Third party auditor.	Clause 7 (Page No. 23, Point No. 3, Column no. 2- Description of Penalty) In case a valid call / Request placed through app at call center is not serviced as per RFP requirement then Call verification penalty shall be applicable. All Calls/requests received at the call center shall be scrutinized and checked by		



Verified calls shall be again verified by Level - 2 team Control room Audit operators hired by TPA (Third party auditor) for monitoring of various parameters including Call verification, Response time ,GPS, Vehicle Maintenance ,Call response, Ambulance booking time, at SwasthyaBhawan State Head Quarters on random sampling of minimum 10% of total valid calls , 01 %Invalid- (Prank ,Nuisance etc.) & Others (Missed call ,Disconnected calls etc.) Received at call center on daily basis.

If it is found that the required services are denied/not provided to the call or the call is not successfully closed due to the fault of service provider running 104-JE then penalty will be imposed for each and every Unserviced call.

It is responsibility of Service provider running 104 -JE to coordinate with integrated call center to ensure service to beneficiaries with in Response time as mentioned in RFP.

Formula for 11 % call auditing @ TPA control room shall be finalized by NHM as per call Logs.

Third party auditor (Level 1 team).

Verified calls shall be again verified by Control room Audit Level -2 team operators hired by TPA (Third party auditor) for monitoring of various parameters including Call verification, Vehicle ,GPS, Response Maintenance ,Call response, Start moving time, at SwasthyaBhawan State Head Ouarterson the basis of random sampling of minimum 10% of total valid calls, 01 %Invalid- (Prank, Nuisance etc.) & Others ( Missed call ,Disconnected calls etc.) Received at call center on daily basis.

If it is found that the required services are denied/not provided to the call or the call is not successfully closed due to the fault of service provider running 104-JE, then penalty shall be imposed for each and every Unserviced call.

It is responsibility of Service provider running 104 -JE to coordinate with integrated call center to ensure service to beneficiaries with in Response time as mentioned in RFP.

Formula for 11 % call auditing @ TPA control room shall be finalized by NHM as per calls/request Logs.

100 % calls/requests audit shall be made by Third Party Auditor(level 1 team) at call center& re verification of 11 % calls( Level 2 team) @ control room.

If mismatch is found @ level 2 TPA audit in various parameters (Call Verification ,Response Time, Start moving time, GPS, Inspection, Vehicle Maintenance/ off-road report) then penalty imposed shall be manner on total extrapolated calls. Thus penalty shall be applicable each & every defaults found @ level 1TPA audit & re verification ofthese reports at level 2 TPA team.

Based on level 2 team audit at control room ,if false reporting /mismatch exceeds in reports at any level( 104 JE Service provider /Call center or TPA(Third party auditor) then notice shall be served to concerned.

97

17	Clause 6.2.7 (Page No.18) 104 –JE fleet -581 vehicleswise Kilometer reading is enclosed at (Annexure 21) for reference of bidders.	Two consecutive warnings may lead to forfeiture of Performance Security and if the services/reporting do not improve thereafter, NHM Rajasthan may consider pre mature termination of the Contract.  Clause 6.2.7 (Page No.19)  104 JE (550)& BASE ambulance (50) which shall be part of 104-JE fleet. Final list of 600 vehicles wise Kilometer reading is enclosed at (Revised Annexure 21) for reference of bidders.
18	Clause 6.1 - Procurements (page no. 17)  The Service provider has to purchase/hire/lease and provide additional New/Fresh 104 JE vehicles in similar lines of existing fleet on turnkey basis as and when directed by MD,NHM as per rates approved in agreement for turnkey vehicles.	Clause 6.1 - Procurements (page no. 17)  The Service provider has to purchase and provide additional New/Fresh 104 JE vehicles in similar lines (As per Vehicles Specifications mentioned at Annexure 28) of existing fleet (Air conditioner enabled) on turnkey basisas mentioned below.  S. Time period Number of Ambulanc date of e/signing of Vehicles agreement have to be operational  Within 60 50 Days  2. Within 90 50 Days  3. Within 120 50 Days  IF ambulances on turnkey basis are not operational within stipulated time, then the amount for the rates agreed for turnkey basis shall be deducted per fault from the total invoice amount raised by service provider for respective district.  Above mentioned Turnkey Ambulances shall be registered in the name of NHM/GoR from the date of commissioning. The ownership of Turnkey ambulances/vehicles (Except Reserve Ambulance) provided during contract period shall



Non-consumable items shall become assets of the program which will have to be handed over to the Government on termination/completion of the program. Proper records of such assets will be maintained in the program accounts by the service provider.

- remain with NHM / GoR after completion of agreement period .
- If Service Provider fails to provide service during contract period and the contract/Agreement terminated prematurely provided in clause 10.4, then Turnkey Ambulances shall remain under possession of NHM/GoR till the New Service Provider takes charge of the services and starts functioning.
- If Turnkey Ambulances are procured by Service Provider on EMI, then EMI tenure for turnkey ambulances should not be more than 5 Years from date of signing of agreement.EMI tenure shall be calculated from the time of deployment of the Ambulance. The EMI of Turnkey Ambulances shall be paid through Escrow Account during the contract period. In case of premature termination of agreement, the remaining amount which is payable to Company from which the vehicles are purchased, shall be governed by termination clause.
- To ensure Uninterrupted emergency services & for monitoring purpose, Reserved ambulances shall also be GPS enabled & equipped in similar lines of same specifications of existing fleet.
- Non-consumable items shall become assets of the program which will have to be handed over to the Government on termination/completion of the program. Proper records of such assets will be maintained in the program accounts by the



service provider. Clause 10.4 (Page No. 31) 19 Clause 10.4 (Page No. 31) **Termination / Suspension of Agreement Termination/Suspension of Agreement** (c) In the event of premature (c) In the event of premature termination of termination of the contract by the Government on the instances other the contract by the Government on the than non-fulfillment/noninstances other than non-fulfillment/ nonperformance of the contractual obligation performance of the contractual obligation by the agency, the balance by the agency, the balance remaining unremaining un-paid amount on account paid amount on account of capital of Operational expenditure as on the expenditure as on the day of termination day of termination shall be released shall be released within six months from within six months from the date of the date of such termination or the issues such termination or the issues are are settled whichever is later. settled whichever is later. In case of Turnkey Ambulances, in the event of premature termination of the contract by the Government, the Government may decide to retain the Turnkey Ambulances or to return them to the Service Provider depending upon the competent decision taken in such circumstances by the State Govt.The payment of remaining EMIs, if any, shall also be affected by the Govt. or the Service Provider as the case may be.The Bidders shall submit an undertaking on a non-Judicial stamp paper of appropriate value(Rs.500/-) accepting this as per Annexure 29. Annexure -7 AGREEMENT( Page no 63) Annexure -7 AGREEMENT( Page no 63) 20 (d)Handover at the time of exit from the (d)Handover at the time of exit from program theprogram (i) The non-consumable assets shall (i)The assets will have to be handed over to have to be handed over to the completion Government Government on completion/termination of the agreement /termination of the agreement in proper working condition. Service in proper working condition. Service Provider shall ensure to send the detailed Provider shall ensure to send the information on monthly basis of the assets detailed information on monthly basis of the assets procured in that procured in that particular particular In case of NHM/GoR owned NHM owned case of (ii)In Ambulances/Vehicles, they have to be Ambulances/Vehicles, they have to be



NHM/Govt. in handed over back to operative and road worthy condition along with thetools/medical equipments provided by RSHS (NHM) or purchased by the Service Provider during currency of the agreement; normal wear and tear is permissible. In case the Ambulance is found non road worthy then the ambulance will be repaired at the risk and cost of the Service provider. In addition to this service provider will be imposed with a penalty @ Rs. 1000/- per day for the number of days the ambulance remain off road due to improper upkeep and handover in nonroadworthy condition.

(iii) In case, Turnkey vehicles are provided during contract period, their possession & ownership will remain with Service Provider after completion of agreement period.

handed over back to NHM/Govt. in operative and road worthy condition tools/medical along with the equipment's provided by RSHS (NHM) or purchased by the Service Provider during currency of the agreement; normal wear and tear is permissible. In case the Ambulance(s) is found non road worthy, then the ambulance will be repaired at the risk and cost of the Service provider.In addition to this, Penalty @ Rs. 1000/- per day shall be imposed on Service Provider for the number of days the ambulance remain off road due to improper upkeep and handover in roadworthy condition.

(iii) In case of Turnkey vehicles, provided during contract period, their possession & ownership will remain with NHM/ GoR after completion of agreement period.

## 21. NA

# Clause No. 12 -Point no 14 (Point no 14-Newely added)

All partners of Consortium shall be liable jointly and severally for the execution of contract in accordance with the contract terms and a copy of the agreement entered into by the joint venture/consortium partners having such a provision shall be submitted with the Bid. A statement to this effect shall be included in the authorization mentioned as above as well as in the bid form and in contract form ( in case of successful bid).

## 22

## **Bid Security**

- Bid Security:- (NIB-page no 10)
   Rs.4 Crores/- (Rupees Four Crores
   Only)
- 2. Cluae 11.8( Bid Security ) -page no 35

Every bidder, if not exempted, participating in the procurement process will be required to

## **Bid Security**

- Bid Security:- Rs.2 Crores/-(Rupees Two Crores Only) &
- 2. Cluae 11.8( Bid Security ) page no 35

Every bidder, if not exempted, participating in the procurement process will be required to furnish the bid security



furnish the bid security as specified in the NIB. The total estimated Project Cost Rs. 200 Crores (Rs. Two Hundred Crores Only) for three years and 4.00 crores (Rs. Four Crores only) have to be submitted by bidder as 2% bid security in the form of Banker's Cheque/ Demand Draft/ BG in favor of "Rajasthan State Health society". The bid security must remain valid thirty days beyond the original or extended validity period of the bid.

as specified in the NIB. The total estimated Project Cost Rs. 200 Crores (Rs. Two Hundred Crores Only) for three years and 2.00 crores (Rs. Two Crores only) have to be submitted by bidder as 1% bid security in the form of Banker's Cheque/ Demand Draft/ BG in favor of "Rajasthan State Health society". The bid security must remain valid thirty days beyond the original or extended validity period of the bid.

Proposal Submission Requirements(
 Proposal Submission
 Requirements)- Page no. 51=
 Point no.4

Bid Security of Rs. 4.00 Crores (Rs. Four crores only) in form of an account payee DD/Banker's Cheque /Bank Guarantee of scheduled Bank in favor of Rajasthan State Health Society, Payable at Jaipur.

3. Proposal Submission
Requirements( 14- Proposal
Submission Requirements)- Page
no. 51=

### Point no.4

Bid Security of Rs. 2.00 Crores (Rs. Two crores only) in form of an account payee DD/Banker's Cheque /Bank Guarantee of scheduled Bank in favor of Rajasthan State Health Society, Payable at Jaipur.

4. ANNEXURE-16:- Checklist of documents CHECKLIST OF DOCUMENTS (Table no .2- Point no 3) - "Bid security DD/Bankers Cheque/ Bank Guarantee for Rs. 4.00 crores (Four Crores only) in favor of "Rajasthan State Health society". Scanned copy with online proposal.

4. ANNEXURE-16:- Checklist of documents CHECKLIST OF DOCUMENTS (Table no .2- Point no 3 )- "Bid security DD/Bankers Cheque/ Bank Guarantee for Rs. 2.00 crores (Two Crores only) in favor of "Rajasthan State Health society". Scanned copy with online proposal.

23

# ANNEXURE2:ACKNOWLEGEMENT& FINANCIAL PROPOSAL (Page no 55)

Point no. 3- If our proposal is accepted, we undertake to deposit security deposit equals to the 5% of the Project Cost arrived at on the basis of financial quote before execution of the formal agreement.

ANNEXURE2:ACKNOWLEGEMENT& FINANCIAL PROPOSAL (Page no. 55)

Point no. 3- If our proposal is accepted, we undertake to deposit security deposit equals to the 2.5% of the Project Cost arrived at on the basis of financial quote before execution of the formal agreement.



	24	Annexure 29 -NA	Annexure 29 ( Attached)
j			

Please note that all Clarification/Corrigendum/ Addendum in bid conditions are the integral part of the bid document. This Corrigendum/ Addendum shall be duly signed and annexed with bid document.

All other terms & conditions remain the same.

(Naresh Kumar Thakral) Mission Director, NHM



# Annexure -21 ( Revised )- Details of 104-Janani Express

S. No.	Ambulance No.	Type Of Vehicle	Make	Year Modal	Progressive K.M. Of Ambulance till 15th July 2020
1	RJ07PA6739	104	Tata Sumo	2014	378853
2	RJ04PA2710	104	Maruti Omni	2012	376900
3	RJ08PA1358	104	Tata Sumo	2014	376777
4	RJ29PA1743	104	Maruti Eeco	2013	376171
5	RJ07PA5603	104	Maruti Omni	2012	375280
6	RJ48PA0012	104	Maruti Eeco	2014	374547
7	RJ04PA2723	104	Maruti Omni	2012	373530
8	RJ22PA3029	104	Maruti Eeco	2014	373148
9	RJ04PA2718	104	Maruti Omni	2012	371484
10	RJ07PA5593	104	Maruti Omni	2012	369317
11	RJ04PA3403	104	Tata Sumo	2014	368421
12	RJ13PA4206	104	Maruti Omni	2012	368381
		104	Tata Sumo	2014	367762
13	RJ30EA1577		Maruti Omni	2012	366333
14	RJ28PA0789	104		2012	363278
15	RJ27PA6057	104	Tata Sumo	2014	362570
16	RJ31PA3479	104	Maruti Eeco		360291
17	RJ37PA1632	104	Tata Sumo	2014	359199
18	RJ20PA7153	104	Tata Sumo	2014	
19	RJ07PA6741	104	Tata Sumo	2014	357840
20	RJ27PA4482	104	Maruti Omni	2012	356809
21	RJ13PA4904	104	Maruti Eeco	2013	356255
22	RJ07PA5599	104	Maruti Omni	2012	355929
23	RJ13PA4906	104	Maruti Eeco	2013	354531
24	RJ13PA4902	104	Maruti Eeco	2013	351705
25	RJ03PA2444	104	Maruti Omni	2012	351467
26	RJ12PA1583	104	Maruti Omni	2012	350478
27	RJ14PC7570	104	Maruti Eeco	2014	350360
28	RJ15PA1523	104	Maruti Omni	2013	349972
29	RJ07PA6740	104	Tata Sumo	2014	349847
30	RJ23PA6772	104	Maruti Eeco	2013	349619
31	RJ10PA5201	104	Maruti Eeco	2014	347270
32	RJ52PA0032	104	Maruti Eeco	2014	346447
33	RJ09PA3268	104	Tata Sumo	2014	346352
34	RJ31PA3481	104	Maruti Eeco	2014	345718
35	RJ08PA1356	104	Tata Sumo	2014	342786
36	RJ15PA1522	104	Maruti Omni	2013	342570
37	RJ03PA2439	104	Maruti Omni	2012	342161
38	RJ14PC7508	104	Maruti Eeco	2014	341266
39	RJ24PA3294	104	Tata Sumo	2014	341111
40	RJ04PA2711	104	Maruti Omni	2012	340729
41	RJ19PA6547	104	Maruti Omni	2012	339841
		104	Tata Sumo	2014	339634
42	RJ09PA3264		Maruti Omni	2012	339469
43	RJ07PA5601	104		2012	338312
44	RJ06PA3521	104	Maruti Omni	2012	337935
45	RJ31PA2884	104	Maruti Omni	2012	337488
46 47	RJ27PA4490 RJ31PA2889	104	Maruti Omni Maruti Omni	2012	337414

	48	RJ27PA4498	104	Maruti Omni	2012	335749
	49	RJ52PA0020	104	Maruti Eeco	2014	335130
	50	RJ26PA0903	104	Maruti Eeco	2014	334330
	51	RJ07PA5607	104	Maruti Omni	2012	333546
	52	RJ13PA4205	104	Maruti Omni	2012	332222
	53	RJ27PA4492	104	Maruti Omni	2012	331945
	54	RJ01PA2242	104	Maruti Omni	2012	331808
	55	RJ17PA1314	104	Tata Sumo	2014	329937
	56	RJ22PA2420	104	Maruti Omni	2012	328105
	57	RJ06PA4247	104	Maruti Eeco	2014	327816
	58	RJ21PA1565	104	Maruti Omni	2012	327733
-	59	RJ01PA2229	104	Maruti Omni	2012	327561
	60	RJ16PA2906	104	Tata Sumo	2014	327461
	61	RJ04PA2713	104	Maruti Omni	2012	326351
	62	RJ17PA1247	104	Tata Sumo	2014	325768
		RJ27PA6028	104	Tata Sumo	2014	325508
	63		104	Maruti Eeco	2013	324442
	64	RJ13PA4907	104	Maruti Omni	2012	323775
	65	RJ04PA2712	<del></del>	Maruti Omni	2012	323521
	66	RJ17PA0985	104		2012	323023
	67	RJ02PA2633	104	Maruti Omni	<del></del>	321429
	68	RJ27PA6064	104	Tata Sumo	2014	321361
	69	RJ03PA3147	104	Tata Sumo	2014	319743
	70	RJ22PA3028	104	Maruti Eeco	2014	
	71	RJ31PA3482	104	Maruti Eeco	2014	319598
	72	RJ12PA1592	104	Maruti Omni	2012	319188
	73	RJ02PA3087	104	Maruti Eeco	2013	318951
	74	RJ10PA4410	104	Maruti Omni	2012	318367
	75	RJ19PA6543	104	Maruti Omni	2012	317266
	76	RJ05PA2547	104	Maruti Eeco	2014	317125
	77	RJ35PA0217	104	Maruti Omni	2012	316845
	78	RJ15PA1533	104	Maruti Omni	2013	314959
	79	RJ36PA2053	104	Maruti Eeco	2014	314666
	80	RJ01PA3091	104	Maruti Eeco	2014	314528
	81	RJ28PA1029	104	Tata Sumo	2014	314175
	82	RJ09PA3265	104	Tata Sumo	2014	313134
	83	RJ19PA8426	104	Maruti Eeco	2013	312234
	84	RJ19PA8434	104	Maruti Eeco	2013	312197
	85	RJ19PA6536	104	Maruti Omni	2012	311057
	86	RJ08PA1359	104	Tata Sumo	2014	310803
	87	RJ07PA7369	104	Maruti Eeco	2014	310633
	88	RJ03PA3148	104	Tata Sumo	2014	309623
	89	RJ31PA3483	104	Maruti Eeco	2014	309373
	90	RJ02PA3082	104	Maruti Eeco	2013	309368
			104	Tata Sumo	2014	308924
ı	91	RJ27PA6037				
	91 92	RJ27PA6037 RJ07PA5602	104	Maruti Omni	2012	308671
				Maruti Omni Maruti Omni	2012 2012	308671 308493
	92 93	RJ07PA5602 RJ31PA2890	104	<del></del>	<del></del>	
	92 93 94	RJ07PA5602 RJ31PA2890 RJ08PA1105	104 104	Maruti Omni	2012	308493
	92 93 94 95	RJ07PA5602 RJ31PA2890 RJ08PA1105 RJ19PA8430	104 104 104 104	Maruti Omni Maruti Omni	2012 2012	308493 308420
	92 93 94 95 96	RJ07PA5602 RJ31PA2890 RJ08PA1105 RJ19PA8430 RJ04PA2719	104 104 104	Maruti Omni Maruti Omni Maruti Eeco Maruti Omni	2012 2012 2013	308493 308420 308343
	92 93 94 95	RJ07PA5602 RJ31PA2890 RJ08PA1105 RJ19PA8430	104 104 104 104 104	Maruti Omni Maruti Omni Maruti Eeco	2012 2012 2013 2012	308493 308420 308343 307935

100	RJ15PA1524	104	Maruti Omni	2013	307025
101	RJ30EA1580	104	Tata Sumo	2014	306184
102	RJ17PA1263	104	Tata Sumo	2014	305464
103	RJ27PA4510	104	Maruti Omni	2012	305284
104	RJ13PA4903	104	Maruti Eeco	2013	305012
105	RJ06PA4245	104	Maruti Eeco	2014	304944
106	RJ11PA0617	104	Maruti Omni	2012	304943
107	RJ21PA2063	104	Tata Sumo	2014	303990
108	RJ31PA2887	104	Maruti Omni	2012	303201
109	RJ02PA2619	104	Maruti Omni	2012	300410
110	RJ26PA0694	104	Maruti Omni	2012	299796
111	RJ03PA3149	104	Tata Sumo	2014	299563
112	RJ27PA4486	104	Maruti Omni	2012	299063
113	RJ14PC7590	104	Maruti Eeco	2014	298604
	RJ30EA1247	104	Maruti Omni	2012	297929
114	RJ04PA2715	104	Maruti Omni	2012	297548
115	RJ14PC2096	104	Maruti Omni	2012	297244
116	·····	104	Maruti Eeco	2013	296726
117	RJ02PA3083		Maruti Eeco	2013	296536
118	RJ26PA0904	104		2014	296402
119.	RJ04PA2714	104	Maruti Omni		295720
120	RJ31PA2886	104	Maruti Omni	2012	
121	RJ03PA2443	104	Maruti Omni	2012	295678
122	RJ13PA4204	104	Maruti Omni	2012	294982
123	RJ14PC2110	104	Maruti Omni	2012	294423
124	RJ23PA5686	104	Maruti Omni	2012	294004
125	RJ33PA0170	104	Maruti Eeco	2014	293997
126	RJ30EA1579	104	Tata Sumo	2014	293701
127	RJ01PA3094	104	Maruti Eeco	2014	293465
128	RJ24PA3120	104	Maruti Omni	2013	292133
129	RJ06PA4251	104	Maruti Eeco	2014	291794
130	RJ08PA1357	104	Tata Sumo	2014	291088
131	RJ04PA2716	104	Maruti Omni	2012	289658
132	RJ29PA1741	104	Maruti Eeco	2013	288400
133	RJ15PA1531	104	Maruti Omni	2013	287989
134	RJ13PA4210	104	Maruti Omni	2012	286685
135	RJ26PA0902	104	Maruti Eeco	2014	286113
136	RJ35PA0319	104	Tata Sumo	2014	285970
137	RJ27PA4504	104	Maruti Omni	2012	285560
138	RJ28PA1030	104	Tata Sumo	2014	283885
139	RJ30EA1581	104	Tata Sumo	2014	283414
140	RJ03PA2446	104	Maruti Omni	2012	282527
141	RJ18PA6138	104	Maruti Eeco	2013	281894
142	RJ19PA6532	104	Maruti Omni	2012	281751
143	RJ15PA1733	104	Tata Sumo	2014	281604
144	RJ13PA4209	104	Maruti Omni	2012	280452
145	RJ10PA4422	104	Maruti Omni	2012	279458
146	RJ17PA1269	104	Tata Sumo	2014	279422
147	RJ11PA0832	104	Tata Sumo	2014	278862
148	RJ29PA1744	104	Maruti Eeco	2013	278765
149	RJ29PA1283	104	Maruti Omni	2012	278358
150	RJ29PA1283	104	Tata Sumo	2014	278133
151	RJ07PA5595	104	Maruti Omni	2012	277535

152	RJ12PA2079	104	Tata Sumo	2014	277405
153	RJ35PA0216	104	Maruti Omni	2012	277114
154	RJ02PA2620	104	Maruti Omni	2012	276655
155	RJ05PA2082	104	Maruti Omni	2012	276403
156	RJ13PA4202	104	Maruti Omni	2012	276354
157	RJ28PA0781	104	Maruti Omni	2012	276289
158	RJ12PA1591	104	Maruti Omni	2012	275984
159	RJ35PA0318	104	Tata Sumo	2014	275129
160	RJ17PA1238	104	Tata Sumo	2014	274174
161	RJ15PA1530	104	Maruti Omni	2013	272177
162	RJ31PA2894	104	Maruti Omni	2012	271625
163	RJ24PA3118	104	Maruti Omni	2013	270381
164	RJ37PA1641	104	Tata Sumo	2014	269946
165	RJ11PA0833	104	Tata Sumo	2014	269944
166	RJ10PA4414	104	Maruti Omni	2012	269435
167	RJ20PA5781	104	Maruti Omni	2012	269384
168	RJ19PA6546	104	Maruti Omni	2012	268832
169	RJ05PA2572	104	Maruti Eeco	2014	268804
	RJ03PA2372 RJ02PA3086	104	Maruti Eeco	2013	268696
170			Maruti Omni	2013	268309
171	RJ17PA0988	104 104	Tata Sumo	2012	267987
172	RJ08PA1360	<del></del>	<del></del>	2014	267618
173	RJ04PA2720	104	Maruti Omni	2012	267501
174	RJ28PA1031	104	Tata Sumo	2014	267489
175	RJ06PA3513	104	Maruti Omni	2012	266196
176	RJ19PA8437	104	Maruti Eeco	2013	265762
177	RJ19PA8432	104	Maruti Eeco		264960
178	RJ27PA6044	104	Tata Sumo	2014	
179	RJ27PA6042	104	Tata Sumo	2014	264681
180	RJ23PA5687	104	Maruti Omni	2012	264426
181	RJ30EA1241	104	Maruti Omni	2012	263615
182	RJ05PA2550	104	Maruti Eeco	2014	262947
183	RJ17PA1250	104	Tata Sumo	2014	262780
184	RJ28PA1035	104	Tata Sumo	2014	262765
185	RJ13PA4899	104	Maruti Eeco	2013	262739
186	RJ11PA0614	104	Maruti Omni	2012	262195
187	RJ12PA1585	104	Maruti Omni	2012	261770
188	RJ09PA2754	104	Maruti Omni	2012	261681
189	RJ06PA4250	104	Maruti Eeco	2014	261538
190	RJ22PA3034	104	Maruti Eeco	2014	261258
191	RJ08PA1355	104	Tata Sumo	2014	260145
192	RJ19PA6548	104	Maruti Omni	2012	260056
193	RJ27PA4497	104	Maruti Omni	2012	259791
194	RJ05PA2545	104	Maruti Eeco	2014	259517
195	RJ15PA1529	104	Maruti Omni	2013	259475
196	RJ08PA1109	104	Maruti Omni	2012	259440
197	RJ13PA4203	104	Maruti Omni	2012	259436
198	RJ21PA1585	104	Maruti Omni	2012	259360
199	RJ15PA1521	104	Maruti Omni	2013	259130
200	RJ24PA3296	104	Tata Sumo	2014	259048
201	RJ08PA1106	104	Maruti Omni	2012	258995
202	RJ03PA2449	104	Maruti Omni	2012	258619
203	RJ18PA5031	104	Maruti Omni	2012	258314

204	RJ02PA3079	104	Maruti Eeco	2013	258203
205	RJ08PA1108	104	Maruti Omni	2013	258020
206	RJ14PC2112	104	Maruti Omni	2012	257557
207	RJ08PA1107	104			<del> </del>
208	RJ12PA1579	104	Maruti Omni	2012	257485
209	RJ24PA3295		Maruti Omni	2012	257454
210	RJ05PA2548	104	Tata Sumo	2014	257001
210		104	Maruti Eeco	2014	256972
212	RJ27PA6045	104	Tata Sumo	2014	256420
213	RJ09PA3267	104	Tata Sumo	2014	255981
	RJ20PA5782	104	Maruti Omni	2012	255824
214	RJ10PA4418	104	Maruti Omni	2012	255561
215	RJ20PA5787	104	Maruti Omni	2012	253918
216	RJ15PA1526	104	Maruti Omni	2013	253138
217	RJ28PA1033	104	Tata Sumo	2014	252930
218	RJ09PA3263	104	Tata Sumo	2014	252625
219	RJ27PA4502	104	Maruti Omni	2012	251948
220	RJ14PC2091	104	Maruti Omni	2012	251899
221	RJ17PA0989	104	Maruti Omni	2012	251574
222	RJ13PA4207	104	Maruti Omni	2012	251517
223	RJ24PA3298	104	Tata Sumo	2014	251488
224	RJ19PA6544	104	Maruti Omni	2012	251401
225	RJ11PA0618	104	Maruti Omni	2012	251315
226	RJ28PA1032	104	Tata Sumo	2014	250455
227	RJ02PA3081	104	Maruti Eeco	2013	250404
228	RJ16PA2905	104	Tata Sumo	2014	250190
229	RJ31PA2893	104	Maruti Omni	2012	249532
230	RJ14PC2092	104	Maruti Omni	2012	24888.7
231	RJ35PA0321	104	Tata Sumo	2014	248800
232	RJ31PA2883	104	Maruti Omni	2012	248611
233	RJ03PA3150	104	Tata Sumo	2014	247599
234	RJ27PA4512	104	Maruti Omni	2012	247066
235	RJ23PA5690	104	Maruti Omni	2012	246966
236	RJ17PA0984	104	Maruti Omni	2012	246450
237	RJ15PA1532	104	Maruti Omni	2013	246426
238	RJ01PA2235	104	Maruti Omni	2012	245990
239	RJ23PA5689	104	Maruti Omni	2012	245972
240	RJ23PA5693	104	Maruti Omni	2012	245875
241	RJ10PA4412	104	Maruti Omni	2012	245694
242	RJ29PA1284	104	Maruti Omni	2012	245048
243	RJ01PA2231	104	Maruti Omni	2012	244750
244	RJ05PA2081	104	Maruti Omni	2012	243318
245	RJ14PC2108	104	Maruti Omni	2012	243101
246	RJ03PA2445	104	Maruti Omni	2012	242927
247	RJ07PA6744	104	Tata Sumo	2014	242744
248	RJ17PA0986	104	Maruti Omni	2012	242729
249	RJ03PA2438	104	Maruti Omni	2012	242189
250	RJ14PC2107	104	Maruti Omni	2012	242136
251	RJ02PA2624	104	Maruti Omni	2012	241719
252	RJ25PA1447	104	Maruti Eeco	2012	241713
253	RJ07PA5594	104	Maruti Omni	2013	241333
253 254	RJ11PA0619	104	Maruti Omni	2012	240481
255	RJ27PA4487	104	Maruti Omni	2012	239840
	102/FM440/	104	I IVIALULI OITIIII	1 4014	233040

256	RJ10PA4415	104	Maruti Omni	2012	330000
257	RJ17PA0993	104	Maruti Omni	2012	239600
258	RJ23PA5685	104	<del>                                     </del>		239134
259	RJ14PC2098	104	Maruti Omni	2012	239089
260	RJ27PA4493	104	Maruti Omni	2012	238923
261	RJ11PA0620	104	Maruti Omni	2012	238286
262	RJ07PA5596	104	Maruti Omni	2012	238280
263	RJ08PA1361		Maruti Omni	2012	237028
264	RJ07PA5598	104	Tata Sumo	2014	236881
265	RJ02PA3085	104	Maruti Omni	2012	236678
266	RJ26PA0899	104	Maruti Eeco	2013	236572
267		104	Maruti Eeco	2014	236233
268	RJ11PA0615	104	Maruti Omni	2012	236040
	RJ28PA0785	104	Maruti Omni	2012	235206
269	RJ14PC2111	104	Maruti Omni	2012	235020
270	RJ21PA2034	104	Tata Sumo	2014	234870
271	RJ21PA1566	104	Maruti Omni	2012	234714
272	RJ05PA2549	104	Maruti Eeco	2014	234148
273	RJ14PC2094	104	Maruti Omni	2012	233203
274	RJ17PA1267	104	Tata Sumo	2014	232423
275	RJ13PA4900	104	Maruti Eeco	2013	231616
276	RJ01PA2241	104	Maruti Omni	2012	230669
277	RJ06PA4244	104	Maruti Eeco	2014	230580
278	RJ20PA5784	104	Maruti Omni	2012	230418
279	RJ11PA0834	104	Tata Sumo	2014	229498
280	RJ26PA0696	104	Maruti Omni	2012	229493
281	RJ04PA2717	104	Maruti Omni	2012	229434
282	RJ35PA0213	104	Maruti Omni	2012	229140
283	RJ02PA2631	104	Maruti Omni	2012	228842
284	RJ14PC2113	104	Maruti Omni	2012	228543
285	RJ27PA6063	104	Tata Sumo	2014	227395
286	RJ21PA1589	104	Maruti Omni	2012	227190
287	RJ36PA2036	104	Maruti Eeco	2014	226846
288	RJ21PA1591	104	Maruti Omni	2013	226086
289	RJ27PA4506	104	Maruti Omni	2012	225811
290	RJ21PA2087	104	Tata Sumo	2014	225701
291	RJ06PA3512	104	Maruti Omni	2012	225283
292	RJ10PA4421	104	Maruti Omni	2012	225264
293	RJ16PA2904	104	Tata Sumo	2013	225210
294	RJ06PA3523	104	Maruti Omni	2012	225000
295	RJ02PA2626	104	Maruti Omni	2012	224436
296	RJ34PA1150	104	Maruti Omni	2012	224425
297	RJ09PA2759	104	Maruti Omni	2012	224231
298	RJ22PA3032	104	Maruti Eeco	2014	223942
299	RJ07PA5604	104	Maruti Omni	2012	223662
300	RJ03PA2441	104	Maruti Omni	2012	223467
301	RJ19PA6531	104	Maruti Omni	2012	222944
302	RJ19PA8436	104	Maruti Eeco	2013	222361
303	RJ31PA2885	104	Maruti Omni	2012	221861
304	RJ34PA1559	104	Tata Sumo	2014	221565
305	RJ10PA4413	104	Maruti Omni	2012	220730
306	RJ35PA0322	104	Tata Sumo	2014	220651
307	RJ29PA1286	104	Maruti Omni	2012	220448

RJ05PA2084   104   Maruti Omni   2012   2   310   RJ22PA3030   104   Maruti Eeco   2014   2   2   311   RJ11PA0616   104   Maruti Eeco   2014   2   2   312   RJ01PA3244   104   Maruti Eeco   2014   2   2   313   RJ12PA2078   104   Tata Sumo   2014   2   2   314   RJ24PA3299   104   Tata Sumo   2014   2   2   315   RJ27PA4509   104   Maruti Omni   2012   2   316   RJ15PA1525   104   Maruti Omni   2013   2   3   3   3   3   3   3   3   3	20442 20166 19875 19866 19645 19606 19325 18595 18203 17729 17667 17246 17120 16705
310         RJ22PA3030         104         Maruti Eeco         2014         2           311         RJ11PA0616         104         Maruti Omni         2012         2           312         RJ01PA3244         104         Maruti Eeco         2014         2           313         RJ12PA2078         104         Tata Sumo         2014         2           314         RJ24PA3299         104         Maruti Omni         2012         2           315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012 <t< td=""><td>19875 19866 19645 19606 19325 18595 18203 17729 17667 17246</td></t<>	19875 19866 19645 19606 19325 18595 18203 17729 17667 17246
311         RJ11PA0616         104         Maruti Omni         2012         2           312         RJ01PA3244         104         Maruti Eeco         2014         2           313         RJ12PA2078         104         Tata Sumo         2014         2           314         RJ24PA3299         104         Maruti Omni         2012         2           315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012 <t< td=""><td>19866 19645 19606 19325 18595 18203 17729 17667 17246</td></t<>	19866 19645 19606 19325 18595 18203 17729 17667 17246
311         RJ11PA0616         104         Maruti Omni         2012         2           312         RJ01PA3244         104         Maruti Eeco         2014         2           313         RJ12PA2078         104         Tata Sumo         2014         2           314         RJ24PA3299         104         Tata Sumo         2014         2           315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012	19645 19606 19325 18595 18203 17729 17667 17246
312         RJ01PA3244         104         Maruti Eeco         2014         2           313         RJ12PA2078         104         Tata Sumo         2014         2           314         RJ24PA3299         104         Tata Sumo         2014         2           315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012	19606 19325 18595 18203 17729 17667 17246
313         RJ12PA2078         104         Tata Sumo         2014         2           314         RJ24PA3299         104         Tata Sumo         2014         2           315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012         2           325         RJ24PA3117         104         Maruti Omni         2013	119325 118595 118203 117729 117667 117246
314         RJ24PA3299         104         Tata Sumo         2014         2           315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012         2           325         RJ24PA3117         104         Maruti Omni         2013         2           326         RJ23PA5692         104         Maruti Omni         2012 <t< td=""><td>18595 18203 17729 17667 17246 17120</td></t<>	18595 18203 17729 17667 17246 17120
315         RJ27PA4509         104         Maruti Omni         2012         2           316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012         2           325         RJ24PA3117         104         Maruti Omni         2013         2           326         RJ23PA5692         104         Maruti Omni         2012         2	18203 17729 17667 17246 17120
316         RJ15PA1525         104         Maruti Omni         2013         2           317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012         2           325         RJ24PA3117         104         Maruti Omni         2013         2           326         RJ23PA5692         104         Maruti Omni         2012         2	17729 17667 17246 17120
317         RJ22PA2425         104         Maruti Omni         2012         2           318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012         2           325         RJ24PA3117         104         Maruti Omni         2013         2           326         RJ23PA5692         104         Maruti Omni         2012         2	217667 217246 217120
318         RJ14PC2095         104         Maruti Omni         2012         2           319         RJ34PA1556         104         Tata Sumo         2014         2           320         RJ23PA5683         104         Maruti Omni         2012         2           321         RJ05PA2080         104         Maruti Omni         2012         2           322         RJ28PA0790         104         Maruti Omni         2012         2           323         RJ19PA6535         104         Maruti Omni         2012         2           324         RJ01PA2230         104         Maruti Omni         2012         2           325         RJ24PA3117         104         Maruti Omni         2013         2           326         RJ23PA5692         104         Maruti Omni         2012         2	17246 17120
319       RJ34PA1556       104       Tata Sumo       2014       2         320       RJ23PA5683       104       Maruti Omni       2012       2         321       RJ05PA2080       104       Maruti Omni       2012       2         322       RJ28PA0790       104       Maruti Omni       2012       2         323       RJ19PA6535       104       Maruti Omni       2012       2         324       RJ01PA2230       104       Maruti Omni       2012       2         325       RJ24PA3117       104       Maruti Omni       2013       2         326       RJ23PA5692       104       Maruti Omni       2012       2	17120
320       RJ23PA5683       104       Maruti Omni       2012       2         321       RJ05PA2080       104       Maruti Omni       2012       2         322       RJ28PA0790       104       Maruti Omni       2012       2         323       RJ19PA6535       104       Maruti Omni       2012       2         324       RJ01PA2230       104       Maruti Omni       2012       2         325       RJ24PA3117       104       Maruti Omni       2013       2         326       RJ23PA5692       104       Maruti Omni       2012       2	
321     RJ05PA2080     104     Maruti Omni     2012     2       322     RJ28PA0790     104     Maruti Omni     2012     2       323     RJ19PA6535     104     Maruti Omni     2012     2       324     RJ01PA2230     104     Maruti Omni     2012     2       325     RJ24PA3117     104     Maruti Omni     2013     2       326     RJ23PA5692     104     Maruti Omni     2012     2	16705
322     RJ28PA0790     104     Maruti Omni     2012     2       323     RJ19PA6535     104     Maruti Omni     2012     2       324     RJ01PA2230     104     Maruti Omni     2012     2       325     RJ24PA3117     104     Maruti Omni     2013     2       326     RJ23PA5692     104     Maruti Omni     2012     2	,10,00
323     RJ19PA6535     104     Maruti Omni     2012     2       324     RJ01PA2230     104     Maruti Omni     2012     2       325     RJ24PA3117     104     Maruti Omni     2013     2       326     RJ23PA5692     104     Maruti Omni     2012     2	16625
324     RJ01PA2230     104     Maruti Omni     2012     2       325     RJ24PA3117     104     Maruti Omni     2013     2       326     RJ23PA5692     104     Maruti Omni     2012     2	16391
325 RJ24PA3117 104 Maruti Omni 2013 2 326 RJ23PA5692 104 Maruti Omni 2012 2	16016
326 RJ23PA5692 104 Maruti Omni 2012 2	15967
	215570
327 RJ01PA2234 104 Maruti Omni 2012 2	215295
	215162
323 13211-07301 201	215092
	215045
330	214876
	214796
	214748
	214402
	213978
	213375
330 10231712207	213209
337	
	213000
	212629
	212484
	212207
	211982
313	211253
	211196
	210846
310 113337.76237	210742
	210443
	210182
343	209770
330 133111237	209242
331 1303172031	209163
332 1001172220 101	209114
333 1020170031	209078
334 1300173317 101 111111111111111111111111	209072
355 RJ17PA0987 104 Maruti Omni 2012	208971
356 RJ14PC2097 104 Maruti Omni 2012	208715
337 1023174140 201 10141411 201	208579
2012	
358 RJ27PA4484 104 Maruti Omni 2012	208431

360	RJ24PA3116	104	Maruti Omni	2013	207820
361	RJ12PA1589	104	Maruti Omni	2012	207536
362	RJ24PA3297	104	Tata Sumo	2014	207461
363	RJ02PA2627	104	Maruti Omni	2012	207427
364	RJ06PA3518	104	Maruti Omni	2012	207332
365	RJ06PA3522	104	Maruti Omni	2012	207201
366	RJ17PA0990	104	Maruti Omni	2012	207010
367	RJ19PA6540	104	Maruti Omni	2012	206515
368	RJ14PC2109	104	Maruti Omni	2012	206022
369	RJ22PA2422	104	Maruti Omni	2012	205976
370	RJ02PA2628	104	Maruti Omni	2012	205881
371	RJ09PA2750	104	Maruti Omni	2012	205536
372	RJ34PA1151	104	Maruti Omni	2012	205379
373	RJ01PA2240	104	Maruti Omni	2012	205192
374	RJ26PA0900	104	Maruti Eeco	2014	205159
375	RJ01PA2236	104	Maruti Omni	2012	204806
376	RJ09PA2752	104	Maruti Omni	2012	204717
377	RJ20PA7334	104	Tata Sumo	2014	204377
378	RJ03PA3151	104	Tata Sumo	2014	204296
	RJ25PA1446	104	Maruti Eeco	2013	204013
379		104	Maruti Omni	2012	203683
380	RJ19PA6534		Maruti Omni	2012	203665
381	RJ19PA6545	104		2012	203398
382	RJ28PA0784	104	Maruti Omni	2012	203398
383	RJ03PA3152	104	Tata Sumo		203298
384	RJ17PA0991	104	Maruti Omni	2012	203288
385	RJ22PA3033	104	Maruti Eeco	2014	
386	RJ21PA2036	104	Tata Sumo	2014	201610
387	RJ30EA1246	104	Maruti Omni	2012	200998
388	RJ09PA2751	104	Maruti Omni	2012	200757
389	RJ25PA1098	104	Maruti Omni	2012	200375
390	RJ17PA0992	104	Maruti Omni	2012	200314
391	RJ16PA2455	104	Maruti Omni	2012	199714
392	RJ19PA8429	104	Maruti Eeco	2013	199692
393	RJ34PA1560	104	Tata Sumo	2014	198934
394	RJ29PA1742	104	Maruti Eeco	2013	198777
395	RJ20PA5780	104	Maruti Omni	2012	197591
396	RJ21PA2035	104	Tata Sumo	2014	197275
397	RJ26PA0692	104	Maruti Omni	2012	197165
398	RJ06PA4246	104	Maruti Eeco	2014	196888
399	RJ30EA1243	104	Maruti Omni	2012	196860
400	RJ27PA4508	104	Maruti Omni	2012	196538
401	RJ34PA1148	104	Maruti Omni	2012	196070
402	RJ24PA3115	104	Maruti Omni	2013	195766
403	RJ05PA2089	104	Maruti Omni	2012	195018
404	RJ02PA2623	104	Maruti Omni	2012	194857
405	RJ27PA6043	104	Tata Sumo	2014	194752
406	RJ26PA0898	104	Maruti Eeco	2014	194738
407	RJ09PA2748	104	Maruti Omni	2012	194382
408	RJ30EA1242	104	Maruti Omni	2012	193143
409	RJ24PA3121	104	Maruti Omni	2013	193008
410	RJ03PA2437	104	Maruti Omni	2012	192766
411	RJ26PA0901	104	Maruti Eeco	2014	192185

412	RJ16PA2446	104	Maruti Omni	2012	192159
413	RJ26PA0690	104	Maruti Omni	2012	191885
414	RJ20PA0090	104	Maruti Omni	2012	191317
415	RJ19PA8433	104	Maruti Eeco	2013	190984
415	RJ19PA6433 RJ06PA4249	104	Maruti Eeco	2013	190384
417	RJ37PA1945	104	Tata Sumo	2015	189949
	RJ25PA1103	104	Maruti Omni	2012	189757
418		104	Maruti Omni	2012	189657
419	RJ09PA2756	104	Maruti Omni	2012	189067
420	RJ02PA2632	104	Maruti Omni	2012	188637
421	RJ29PA1290	,	Maruti Omni	2012	188399
422	RJ23PA5691	104	<del></del>	2012	188158
423	RJ04PA2721	104	Maruti Omni	<del></del>	187672
424	RJ03PA2447	104	Maruti Omni	2012	
425	RJ20PA5785	104	Maruti Omni	2012	187380
426	RJ19PA6542	104	Maruti Omni	2012	187367
427	RJ21PA1854	104	Maruti Omni	2013	187188
428	RJ25PA1102	104	Maruti Omni	2012	186348
429	RJ28PA0783	104	Maruti Omni	2012	186318
430	RJ34PA1153	104	Maruti Omni	2012	186075
431	RJ30EA1248	104	Maruti Omni	2012	185234
432	RJ17PA1221	Base	Tata Winger	2013	185227
433	RJ22PA2423	104	Maruti Omni	2012	184930
434	RJ02PA2634	104	Maruti Omni	2012	184231
435	RJ26PA0699	104	Maruti Omni	2012	184203
436	RJ34PA1152	104	Maruti Omni	2012	183780
437	RJ17PA1276	Base	Tata Winger	2013	183083
438	RJ29PA1285	104	Maruti Omni	2012	183053
439	RJ19PA6539	104	Maruti Omni	2012	182843
440	RJ08PA1110	104	Maruti Omni	2012	182645
441	RJ06PA3516	104	Maruti Omni	2012	182399
442	RJ29PA1720	Base	Tata Winger	2013	182358
443	RJ25PA1099	104	Maruti Omni	2012	182141
444	RJ18PA5030	104	Maruti Omni	2012	182046
445	RJ01PA2238	104	Maruti Omni	2012	181792
446	RJ12PA1584	104	Maruti Omni	2012	181771
447	RJ25PA1449	104	Maruti Eeco	2013	181738
448	RJ06PA4252	104	Maruti Eeco	2014	181382
449	RJ21PA1581	104	Maruti Omni	2012	181209
450	RJ25PA1096	104	Maruti Omni	2012	181193
451	RJ20PA5783	104	Maruti Omni	2012	180709
452	RJ02PA2635	104	Maruti Omni	2012	180632
453	RJ03PA2440	104	Maruti Omni	2012	180543
454	RJ30EA1245	104	Maruti Omni	2012	180228
455	RJ01PA2232	104	Maruti Omni	2012	179908
456	RJ10PA4419	104	Maruti Omni	2012	179891
457	RJ35PA0218	104	Maruti Omni	2012	179138
458	RJ07PA5606	104	Maruti Omni	2012	178554
459	RJ06PA3520	104	Maruti Omni	2012	177759
460	RJ22PA2421	104	Maruti Omni	2012	177139
461	RJ30EA1249	104	Maruti Omni	2012	177050
462	RJ27PA4494	104	Maruti Omni	2012	176834
463	RJ27PA4507	104	Maruti Omni	2012	176732

464	RJ34PA1155	104	Maruti Omni	2012	176407
465	RJ05PA2090	104	Maruti Omni	2012	176403
466	RJ14PC2114	104	Maruti Omni	2012	176359
467	RJ26PA0698	104	Maruti Omni	2012	176050
468	RJ19PA6541	104	Maruti Omni	2012	175592
469	RJ14PC5892	Base	Tata Winger	2013	175496
470	RJ05PA2552	104	Maruti Eeco	2014	173904
471	RJ06PA3514	104	Maruti Omni	2012	173506
472	RJ34PA1558	104	Tata Sumo	2014	173272
473	RJ12PA1962	Base	Tata Winger	2013	172805
474	RJ19PA6538	104	Maruti Omni	2012	172620
475	RJ12PA1581	104	Maruti Omni	2012	172296
476	RJ30EA1244	104	Maruti Omni	2012	172121
477	RJ12PA1580	104	Maruti Omni	2012	172052
478	RJ08PA1104	104	Maruti Omni	2012	171942
479	RJ12PA2033	Base	Tata Winger	2013	171930
480	RJ09PA2747	104	Maruti Omni	2012	171104
481	RJ17PA1236	Base	Tata Winger	2013	170876
482	RJ32PA2250	Base	Tata Winger	2012	169818
483	RJ26PA0688	104	Maruti Omni	2012	169547
484	RJ18PA6114	Base	Tata Winger	2013	169527
485	RJ27PA4495	104	Maruti Omni	2012	169480
486	RJ33PA0165	104	Tata Sumo	2014	169346
487	RJ05PA2088	104	Maruti Omni	2012	168957
488	RJ25PA1444	104	Maruti Eeco	2013	168653
489	RJ05PA2546	104	Maruti Eeco	2014	168627
490	RJ26PA0870	Base	Tata Winger	2012	168222
	RJ02PA2629	104	Maruti Omni	2012	168218
491 492	RJ24PA3119	104	Maruti Omni	2013	167516
		104	Maruti Omni	2013	167196
493	RJ30EA1251	104	Maruti Omni	2012	166412
494	RJ28PA0787		Maruti Eeco	2012	166338
495	RJ06PA4248	104		2014	166270
496	RJ21PA1590	104	Maruti Omni	2012	166216
497	RJ34PA1154	104	Maruti Omni	2012	165935
498	RJ29PA1289	104	Maruti Omni	2012	164890
499	RJ26PA0689	104	Maruti Omni	2013	164830
500	RJ34PA1544	Base	Tata Winger	2013	162756
501	RJ05PA2085	104	Maruti Omni		162613
502	RJ23PA5682	104	Maruti Omni	2012	
503	RJ04PA2722	104	Maruti Omni	2012	162470
504	RJ12PA1586	104	Maruti Omni	2012	162104
505	RJ29PA1288	104	Maruti Omni	2012	162092
506	RJ35PA0295	Base	Tata Winger	2013	161791
507	RJ18PA5038	104	Maruti Omni	2012	161482
508	RJ28PA0788	104	Maruti Omni	2012	160095
509	RJ18PA5029	104	Maruti Omni	2012	159588
510	RJ21PA1567	104	Maruti Omni	2012	158943
511	RJ18PA5033	104	Maruti Omni	2012	158884
512	RJ27PA4503	104	Maruti Omni	2012	157971
513	RJ14PC2099	104	Maruti Omni	2012	157633
514	RJ25PA1105	104	Maruti Omni	2012	157355
515	RJ13PA4908	Base	Tata Winger	2013	156726

516	RJ12PA1587	104	Maruti Omni	2012	156299
517	RJ10PA4420	104	Maruti Omni	2012	155961
518	RJ21PA1582	104	Maruti Omni	2012	155855
519	RJ25PA1097	104	Maruti Omni	2012	155465
520	RJ16PA2452	104	Maruti Omni	2012	155244
521	RJ16PA2450	104	Maruti Omni	2012	155085
522	RJ16PA2445	104	Maruti Omni	2012	154729
523	RJ27PA4501	104	Maruti Omni	2012	154378
524	RJ26PA0693	104	Maruti Omni	2012	152890
525	RJ19PA8435	104	Maruti Eeco	2013	152875
526	RJ14PC5966	Base	Tata Winger	2013	152819
527	RJ25PA1100	104	Maruti Omni	2012	151631
528	RJ12PA1588	104	Maruti Omni	2012	151348
529	RJ05PA2478	Base	Tata Winger	2013	150346
530	RJ16PA2457	104	Maruti Omni	2012	149620
531	RJ28PA0782	104	Maruti Omni	2012	148462
532	RJ12PA1590	104	Maruti Omni	2012	148353
533	RJ05PA2083	104	Maruti Omni	2012	147925
534	RJ35PA0214	104	Maruti Omni	2012	146339
535	RJ24PA3249	Base	Tata Winger	2013	146200
536	RJ27PA5960	Base	Tata Winger	2013	145186
537	RJ02PA2621	104	Maruti Omni	2012	143853
538	RJ27PA5861	Base	Tata Winger	2013	143111
539	RJ26PA0868	Base	Tata Winger	2013	142691
540	RJ07PA6937	Base	Tata Winger	2013	141301
541	RJ11PA0839	Base	Tata Winger	2013	141170
542	RJ14PC5945	Base	Tata Winger	2013	140678
543	RJ12PA1582	104	Maruti Omni	2012	140378
544	RJ18PA5037	104	Maruti Omni	2012	140332
545	RJ09PA2757	104	Maruti Omni	2012	139313
546	RJ25PA1104	104	Maruti Omni	2012	139172
547	RJ16PA2454	104	Maruti Omni	2012	139101
548	RJ05PA2092	104	Maruti Omni	2012	137616
549	RJ14PC6000	Base	Tata Winger	2013	136802
550	RJ05PA2087	104	Maruti Omni	2012	136388
551	RJ09PA2749	104	Maruti Omni	2012	136259
552	RJ14PC7299	Base	Tata Winger	2013	136139
553	RJ22PA2424	104	Maruti Omni	2012	135865
554	RJ27PA4505	104	Maruti Omni	2012	135832
555	RJ03PA2448	104	Maruti Omni	2012	135711
556	RJ02PA2622	104	Maruti Omni	2012	133498
557	RJ09PA2758	104	Maruti Omni	2012	130563
558	RJ35PA0215	104	Maruti Omni	2012	129795
559	RJ16PA2448	104	Maruti Omni	2012	129511
560	RJ16PA2444	104	Maruti Omni	2012	127667
561	RJ27PA5862	Base	Tata Winger	2013	126402
562	RJ03PA3146	104	Tata Sumo	2014	125595
563	RJ03PA3146 RJ01PA2233	104	Maruti Omni	2012	125519
	RJ14PC5912	Base	Tata Winger	2012	123719
564 565		Base	Tata Winger	2013	123474
566	RJ18PA6041	104	Maruti Omni	2013	123289
ססכ	RJ26PA0697 RJ18PA6159	Base	Tata Winger	2012	119699

568	RJ16PA2447	104	Maruti Omni	2012	119495
569	RJ12PA1960	Base	Tata Winger	2013	115751
570	RJ11PA0823	Base	Tata Winger	2013	114976
571	RJ16PA2453	104	Maruti Omni	2012	114815
572	RJ01PA2239	104	Maruti Omni	2012	113726
573	RJ27PA6041	Base	Tata Winger	2013	113360
574	RJ16PA2449	104	Maruti Omni	2012	113244
575	RJ14PC5965	Base	Tata Winger	2013	112645
576	RJ18PA5035	104	Maruti Omni	2012	111498
577	RJ11PA0836	Base	Tata Winger	2013	109863
578	RJ35PA0296	Base	Tata Winger	2013	107779
579	RJ18PA6118	Base	Tata Winger	2013	104344
580	RJ16PA2451	104	Maruti Omni	2012	104073
581	RJ30EA1562	Base	Tata Winger	2013	101061
582	RJ21PA1588	104	Maruti Omni	2012	100639
583	RJ11PA0821	Base	Tata Winger	2012	99514
584	RJ12PA1967	Base	Tata Winger	2013	90848
585	RJ14PC5880	Base	Tata Winger	2013	90126
586	RJ30EA1561	Base	Tata Winger	2013	88280
587	RJ14PC6398	Base	Tata Winger	2013	87399
588	RJ34PA1543	Base	Tata Winger	2013	86100
589	RJ21PA1586	104	Maruti Omni	2012	84675
590	RJ11PA0814	Base	Tata Winger	2013	84274
591	RJ16PA2456	104	Maruti Omni	2012	84144
592	RJ18PA5032	104	Maruti Omni	2012	80440
593	RJ38PA0214	Base	Tata Winger	2013	76307
594	RJ11PA0859	Base	Tata Winger	2013	75588
595	RJ16PA2443	104	Maruti Omni	2012	71864
596	RJ21PA1977	Base	Tata Winger	2013	68162
597	RJ27PA5828	Base	Tata Winger	2013	61072
598	RJ27PA5863	Base	Tata Winger	2013	58471
599	RJ27PA6125	Base	Tata Winger	2013	49003
600	RJ22PA2940	Base	Tata Winger	2013	42052

## ANNEXURE-27.

GVK EMRI

GVKEMRI/PPP/RJ/July/34

Date: 24 July 2020

To,

The Mission Director, NHM, Swasthya Bhawan, Jaipur (Rajasthan)

Subject: EMT/Pilot salary details

Reference: Your letter no. 112 dated 22 July 2020

Dear Sir,

With Reference to your letter no. 112 dated 22 July 2020 we would like to apprise that there is no salary norm followed by us for 8 hours for ambulance EMT/ Pilots as keeping the emergency nature of ambulance operations, the EMT/Pilot work on 12 hrs shift. Based on the 12 hrs shift working the Gross salary per month for pilot on 07.11.2019 was Rs 9566 and gross salary per month of EMT was Rs 9880.

For,

**GVK Emergency Management and Research Institute** 

Praveen Sawant

State Head Rajasthan

Rajasthan Rajasthan

CC: PD NHM

SVK Emergency Management and Research Institute SIHFW Building, South of Doordarshan Kendra, halana Institutional Area, Jaipur - 302 004, Rajasthan, India

Phone : +91-141-2701-108 www.emri.in

Emergency Ambulance Services Healthcare Outreach Services Road Safety Initiatives Police Helpline Civic Services Helpline Emergency Medicine Education Women Counselling & Rescue Mobile Veterinary Services Student Counselling Helpline CSR Partnerships

Head Office: GVK Emergency Management and Research Institute, Devar Yamzal, Medchal Road, Secunderabad - 500 078, Telangana, India. 1+91 40 2346 2222/2600 F + 91 40 2346 2178

## ANNEXURE 29: FORMAT for UNDERTAKING Turnkey Ambulance

I/We accept the condition mentioned in Clause 10.4 regarding turnkey ambulances which will decide by state government as and when condition of premature termination is invoked.

Place:		
	(	)
Date:	Signature of authorizeds	ignatory
	Designation and Officia	ıl seal

Note:- Annexure 29 of undertaking for turnkey ambulance is to be submitted on stamp paper of Rs. 500